

Contract ID: SC-INF01-1469  
Our File#:18-304


**Sanayut Consulting Professional  
Engineers Corporation**

## **Juk Territorial Park Tower Foundation Pile Condition Assessment**

**PREPARED BY:**

Sanayut Consulting Professional Engineers Corporation  
PO Box 3033 Inuvik, NT X0E 0T0





## Covering Letter

August 14, 2018

Government of the Northwest Territories  
Department of Infrastructure  
Projects Division  
3rd floor, GNWT Multiuse Building  
Bag Service #1  
106 Veterans Way  
Inuvik, NT X0E 0T0  
**Attn: Joao Nuncio**

Dear Sir:

**Regarding: Existing Pile Foundation Investigation – Juk Territorial Park Tower**  
**Location: Juk Territorial Park, near Inuvik, NT**

**Sanayut Consulting Professional Engineers Corporation (Sanayut)** is pleased to provide the following report regarding the foundation pile condition assessment for the above-referenced structure.

This report has been prepared under my direct supervision.

We appreciate the opportunity to work with you. Please feel free to contact us if you have any questions regarding the enclosed report.

Sincerely,  
**Sanayut Consulting Professional Engineers Corporation**



Mark Hasegawa, P.Eng.  
Enclosures  
MH/cms

## Table of Contents

### Covering Letter

<b>EXECUTIVE SUMMARY .....</b>	<b>1</b>
<b>1. EXISTING CONDITIONS .....</b>	<b>2</b>
<b>2. METHODOLOGY .....</b>	<b>2</b>
2.1 Project Objectives .....	2
2.2 Project Implementation .....	2
2.2.1 Data Acquisition .....	2
2.2.2 Code Review and References .....	2
2.2.3 Site Visit .....	2
<b>3. SUMMARY OF OBSERVATIONS.....</b>	<b>3</b>
<b>4. REPAIR/REPLACEMENT RECOMMENDATIONS.....</b>	<b>3</b>
<b>5. COST ANALYSIS .....</b>	<b>3</b>
<b>6. SUMMARY AND CONCLUSIONS .....</b>	<b>4</b>
<b>REFERENCES .....</b>	<b>5</b>

### List of Tables

Table 1. Summary of Pile Observations .....	3
---	---

### Appendices

<b>APPENDIX A. PILE INVENTORY FORM &amp; FIGURE</b>	
<b>APPENDIX B. PHOTOGRAPHS</b>	

## EXECUTIVE SUMMARY

An assessment of the existing pile foundation of the lookout tower at the Juk Territorial Park located approximately five km outside Inuvik, NT was conducted on July 30, 2018.

The wooden pile foundation that formerly supported the tower had been removed and replaced with steel piles supporting steel beams spanning under the tower. During the pile inspection on July 30, 2018, the location and condition of each pile supporting the lookout tower was observed and documented. An assessment of the extent of pile deterioration was conducted on each pile by exposing buried portions of each pile and observing conditions. In addition, an evaluation of existing overland drainage patterns was conducted. The drainage flows from northwest to southeast and no ponding or puddling was observed around or beneath the tower.

The results of this report indicate that the steel piles are in relatively good condition with minor rust and flaking on the surface. Based on this analysis the foundation appears to be performing as designed.

## 1. EXISTING CONDITIONS

The Juk Territorial Park tower rests on six, 10-inch diameter exterior steel piles and one, 14" diameter, large central steel pile/column that support steel beams that in turn support the wood frame tower structure. The dimensions and pile spacings are shown on [Figure 1](#), [Appendix A](#) and further described in subsequent sections.

## 2. METHODOLOGY

The following section includes a summary of assessment methodology for the existing pile conditions as documented in the previous section.

### 2.1 Project Objectives

The project objectives stated in the TOR are as follows:

“The GNWT requires consultant engineering services to complete a foundation investigation for wooden pile foundations for Beaufort Delta and Sahtu buildings and to determine remedial work required which may include the change of foundation type as part of a final report.”

### 2.2 Project Implementation

The following is the action taken to fulfill the scope of work set forth in the TOR.

#### 2.2.1 Data Acquisition

No design or construction documentation of the building such as as-builts, building plans or date of construction could be identified.

#### 2.2.2 Code Review and References

Code and reference reviews were conducted of key codes and regulations and include the following applicable Acts, Standards and Guidelines:

1. *Good Building Practice for Northern Facilities*, Government of the Northwest Territories
2. National Building Code 2010
3. *GNWT Deteriorated Untreated Wood Piles: Cause, Detection and Correction* document
4. Pile remediation contractors.

Since the tower had already been repaired and there are no wood piles, no costing or recommendations with respect to repairs were made.

#### 2.2.3 Site Visit

A site visit and inspection of each pile was conducted on July 30, 2018. The inspection for each pile included:

- ) Visual observation of the site and existing overland drainage patterns. Site drainage was observed to determine if it was potentially impacting the piles and possibly enhancing pile deterioration.
- ) Observations and measurements as to the general building footprint, pile types, sizes, and dimensions between piles (this information is summarized on [Figure 1](#))
- ) Excavation around each pile up to 180 degrees and down to a depth of 500mm below ground surface
- ) Photographs were also taken and a selection of photos illustrating findings is attached (refer to [Appendix B–Photographs](#)).

Steel Pile Inspection

- ) Visual inspection of pile condition
- ) Scratch test with screwdriver to determine depth of rust penetration if any present.

### 3. SUMMARY OF OBSERVATIONS

The results of this analysis are summarized in **Figure 1** ([Appendix A](#)) and **Table 1** (below) and the pile inventory form in [Appendix A](#). The piles have been classified based on the structural criteria set forth in the previous section. Key parameters evaluated included:

- ) Diameter of pile
- ) Depth of deterioration
- ) Vertical extent of deterioration
- ) Existence of drainage issues or standing water.
- ) Remaining pile diameter with solid material

The tower is currently supported by 6 exterior steel piles, each being 10 inches in diameter. The central pile/column is a 14" diameter steel pile (refer to Figure 1). The ground around each pile was excavated to a maximum depth of 500mm below ground ensuring that each pile was exposed up to 180 degrees around for inspection. A visual inspection as well as a "scratch" test was performed for each steel pile. The results of the site inspection showed that each steel pile had minimal surface rust with no penetration or flaking steel. There was no standing surface water observed at the site and the overland drainage direction appears to be to the southeast.

**Table 1. Summary of Pile Observations**

	Number of piles	Recommendations
<b>Total Piles</b>	7	
<b>&lt; 10% damage</b>		
<b>10-25% damage</b>		
<b>25-50% damage</b>		
<b>&gt;50% damage</b>		
<b>Replaced with steel piles</b>	7	none
<b>Not inspected</b>		

### 4. REPAIR/REPLACEMENT RECOMMENDATIONS

Based on this analysis, the existing steel piles are in good working condition and any observed rust or deterioration was minimal and not of concern. No repair or replacement action is recommended at this time.

### 5. COST ANALYSIS

No cost analysis was performed as no repair or replacement actions are recommended at this time.

## 6. SUMMARY AND CONCLUSIONS

An assessment of the foundations of the office located at the aforementioned address was conducted. An area map showing the location of the site is shown in **Figure 1**, [Appendix A](#).

The wooden pile foundation that formerly supported the tower had been removed and replaced with 7 steel piles supporting steel beams spanning under the structure. The location and condition of the piles were documented. An assessment of the extent of pile deterioration was conducted on each pile by exposing buried portions of the pile and observing conditions. In addition, an evaluation of existing drainage patterns was conducted. The drainage flows from northwest to southeast and no ponding or puddling was observed. No changes to the site grading around and/or beneath the existing building are recommended.

The results of this report indicate that the steel piles are in relatively good condition with only surface rust observed on the exterior of the steel piles. Based on this analysis, the foundation appears to be performing as designed and no repairs or replacement actions are recommended at this time.

## REFERENCES

1. *Untreated Submerged Timber Pile Foundations: Part 1: Understanding Biodegradation and Compressive Strength* Dec, 2013 By Giuliana Zelada-Tumialan, P.E., William Konicki, P.E., Philip Westover, P.E. and Milan Vatovec, Ph.D., P.E. In *Articles, Structural Forensics*.
2. *Untreated Submerged Timber Pile Foundations: Part 2 – Estimating Remaining Service Life* Jan, 2014 By Giuliana Zelada-Tumialan, P.E., William Konicki, P.E., Philip Westover, P.E. and Milan Vatovec, Ph.D., P.E. In *Articles, Structural Forensics*.
3. *Deteriorated Untreated Wood Piles: Cause, Detection and Correction*. By Technical Support Services, Asset Management Division, Public Works and Services, Government of the NWT <http://www.pws.gov.nt.ca>



## APPENDIX A

### PILE INVENTORY FORM & FIGURE

# Pile Inventory Form

**BUILDING ASSET NUMBER:**

**BUILDING NAME:** JUK PARK TOWER, INUVIK, NT

**TOTAL NUMBER OF PILES:** 7

**DATE INSPECTED:** 19-Jun-18

**WATER PONDING UNDER BUILDING:** No

**YEAR OF PILE INSTALLATION:** Unknown

**ADDITION:** No

**SKIRTING AROUND BUILDING (Y/N):** No



**WEATHER CONDITIONS:** Overcast

**TEMPERATURE:** 8°C

PILE TYPE	
W	WOOD
S	STEEL
C	CONCRETE

	Definition - Pile Condition	Range of Rot	Count in each range	Percentage in each Range
<b>A</b>	Little or no rot detected, No repair req'd	0 - 10%	N/A	N/A
<b>B</b>	Rotted, requires monitoring	10 - 25%	N/A	N/A
<b>C</b>	Rotted, requires repair	25 - 50%	N/A	N/A
<b>D</b>	Rotted, requires immediate blocking	50 to 100%	N/A	N/A

No.	Pile Type	Pile Currently Blocked	Previously Repaired	Depth of Rot Detected	Pile Diameter	Pile Circumference	Original Area (Cross section)	Cross sectional Area of Rot	Percent Rot (Cross section)	Moisture	Pile Condition		Date Pile Blocked	Date Pile Repaired	Date Boron Treatment	Comments/Remarks
	W, S, C	Y/N	Y/N	inches	inches	inches	square inches	square inches	%	%	Def	Date				
1	S	N	Y		10								2018-06-19			Surface rust
2	S	N	Y		10								2018-06-19			Surface rust/some flaking
3	S	N	Y		10								2018-06-19			Surface rust/some flaking
4	S	N	Y		10								2018-06-19			Surface rust
5	S	N	Y		10								2018-06-19			Surface rust/some flaking
6	S	N	Y		10								2018-06-19			Surface rust/some flaking
7	S	N	Y		14								2018-06-19			Surface rust



**LEGEND**

- STEEL PILE - 10" DIAMETER
- ① PILE NUMBER
- NR NO RUST
- SR SURFACE RUST
- FR FLAKING RUST
- ← OVERLAND DRAINAGE DIRECTION

**NOTE:**

- BUILDING DIMENSIONS SHOWN ARE APPROXIMATE AND FOR REFERENCE ONLY
- NO STANDING WATER OR PONDING OBSERVED AT THE SITE

DRAWING STATUS				<b>FOR REPORT</b>			
#	REVISION			DATE	BY		
<b>NOTES</b>							
THIS IS A COPYRIGHT DRAWING AND SHALL NOT BE REPRODUCED IN ANY FORM WITHOUT WRITTEN PERMISSION OF THE ENGINEER							
CONTRACTOR TO CHECK AND VERIFY ALL DIMENSIONS BEFORE CONSTRUCTION, ANY ERRORS AND OMISSIONS SHALL BE REPORTED TO THE ENGINEER IMMEDIATELY							
DRAWING SHALL NOT BE USED FOR CONSTRUCTION UNTIL APPROVED							
DO NOT SCALE THE DRAWING							
ALL CONSTRUCTION SHALL BE IN ACCORDANCE WITH THE LATEST CODES, MAY IT BE CONSTRUCTION, MECHANICAL, ETC							

CLIENT		GOVERNMENT OF NWT	
PROJECT TITLE		PILE ASSESSMENT JULY 30, 2018	
DRAWING TITLE		JUK TERRITORIAL PARK TOWER INUVIK, NT	



INSPECTED BY	MO
DRAWN	MO
CHECKED	MH
APPROVED	MH
SCALE	NTS

PROJECT NUMBER	18-304
VERSION NUMBER	IFA1-1
DATE DRAWN	JULY 30, 2018
SHEET NUMBER	<b>FIG. 1</b>

## APPENDIX B

### PHOTOGRAPHS



Photograph 1

Pile #1  
Flaking rust observed



Photograph 2

Pile #2  
Flaking rust observed



Photograph 3

Pile #3  
Surface rust observed



Photograph 4

Pile #4  
Surface rust observed



Photograph 5

Pile #5  
Surface rust observed



Photograph 6

Pile #6  
Flaking rust observed



Photograph 7

Center Pile/Column  
Surface rust observed



Photograph 8

Exterior of tower



Photograph 9

Interior steel beam framework of tower with center column visible in foreground.